



USB Connection



C1\_Out

P01

} P04, P06 To Relay Board



Power Supply

+5V

To Relay Board

Title: Computer Motor Control		
Size: A		Rev:
Scale: N/A	Sheet: 1 of 1	